



## WARRANTY ADDENDUM

This addendum to the aboveground warranty is to cover corrosion when the pool is installed half way in the ground. It does not cover structural damage due to improper installation procedures.

The conditions of our standard warranty are in full force when the pool is installed half way in the ground if the following conditions are met:

1. Pool must be full prior to backfilling.
2. Proper backfill material must be used i.e. sand or sifted soil with no rocks or sharp objects.
3. Do not damage wall or frame during backfilling.
4. Backfill must be graded away from pool ten degrees.
5. Pool must be kept one half full of water at all times. If pool must be drained at any time to service or repair the liner, it must be done during the dry season when the ground water level is below the level of the pool bottom, so as not to collapse pool inward.
6. Region of country where this type of installation is occurring must be south of standard frost belt.

Any damage caused during backfill operation or draining of the pool will void warranty. CORNELIUS will not be responsible for any inward collapse of pool wall or frame caused by this. CORNELIUS will also not be responsible for any pool failures resulting from excessive water conditions such as flooding due to rainfall or other conditions.

Cornelius Industries Inc.  
15 Cushman Rd.  
St. Catharines, Ontario, Canada  
L2M 6S7  
(416) 688-2612

Cornelius Pools Inc.  
166 Sweeney St.  
N. Tonawanda, N.Y., U.S.A.  
14120  
(716) 692-4955

Type O pools are non-diving pools: PLEASE DO NOT DIVE!