



## WARRANTY ADDENDUM

This addendum to the above ground pool warranty covers corrosion when the pool is installed halfway in the ground. It does not cover structural damage due to improper installation procedures or frost heave.

The conditions of our standard warranty are in full force when the pool is installed halfway in the ground if the following conditions are met:

1. The pool must be full prior to backfilling.
2. Proper backfill material, such as sand or sifted soil, must be used, with no rocks or sharp edges.
3. Neither the wall, the frame, nor any of the coatings can be damaged during the backfilling process.
4. Backfill must be graded away from the pool 10°.
5. The pool must be kept  $\frac{3}{4}$  full of water at all times. If the pool must be drained at any time to service or to repair the liner, it must be done during the dry season when the groundwater level is below the level of the pool bottom to avoid the pool collapsing inward.

Any damage caused during the backfill process or as a result of draining the pool will void the warranty. Sunsports will not be responsible for any inward collapse of the pool wall or frame under any circumstances. Sunsports will not be responsible for any pool failure resulting from excessive water conditions, such as flooding due to rainfall, or other conditions.

Sunsports  
50 Cabot Court  
Hauppauge, NY 11788  
(631) 951-9800

Rev. 1/2020